全漢企業股份有限公司

安規證書

料號	:	
Model Name		YVIC0600AM,YVIC0450AM,YVIC0300AM,YVIC0600AH,YVIC0450AH,YVIC0300AH,YVIC0600BM,YVIC0450BM,YVIC0300BM,YNEB0450BM,YNEB0450CM
版次	:	03
文件編號	:	SFD-00004249
作者	:	dick/李高宗(3Y)
Model No/Type	:	YVIC0600AM,YVIC0450AM,YVIC0300AM,YVIC0600AH,YVIC0450AH,YVIC0300AH,YVIC0600BM,YVIC0450BM,YVIC0300BM,YNEB0450BM,YNEB0450CM
SFA NO.	:	-
Trade mark	:	3Y
安規種類	:	UL/cUL 62368
發行日期	:	2020/03/24 17:26:38
備註	:	UL證書(移除空格)

台灣 桃園市桃園區 330 建國東路 22 號
No. 22, Jianguo E. Rd., Taoyuan Dist., Taoyuan City 330, Taiwan(R.O.C)
TEL：+886-3-375-9888　FAX：+886-3-375-6966

文件資料管制 文件資料管制 文件資料管制 All rights reserved

CERTIFICATE OF COMPLIANCE

Certificate Number	20190522-E142723
Report Reference	E142723-A6022-UL
Issue Date	2019-MAY-22
Issued to:	3Y POWER TECHNOLOGY (TAIWAN) INC 2nd Fl 576,578 Minsheng N Rd Sec 1 Gueishan District Taoyuan 333 TAIWAN
This certificate confirms that representative samples of	COMPONENT - POWER SUPPLIES FOR USE WITH AUDIO/VIDEO, INFORMATION AND COMMUNICATION TECHNOLOGY EQUIPMENT "See Addendum Page" Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.
Standard(s) for Safety:	UL 62368-1 & CAN/CSA C22.2 No. 62368-1-14 - Audio/video, information and communication technology equipment Part 1: Safety requirements
Additional Information:	See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

1/3禁止翻印外洩 All rights reserved SFD-00004249-R03.pdf 建立時間:2020-03-24 17:26:39

文件資料管制 文件資料管制 文件資料管制 All rights reserved

CERTIFICATE OF COMPLIANCE

Certificate Number	20190522-E142723
Report Reference	E142723-A6022-UL
Issue Date	2019-MAY-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Redundant Power Supply and Power Module

Redundant Power Supply: YVIC0300AH, YVIC0450AH, and YVIC0600AH
Power Module: YVIC0300AM, YVIC0300BM, YVIC0450AM, YVIC0450BM, YVIC0600AM, YVIC0600BM, YNEB0450BM, and YNEB0450CM

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

2/3禁止翻印外洩 All rights reserved SFD-00004249-R03.pdf 建立時間:2020-03-24 17:26:39

文件資料管制 文件資料管制 文件資料管制 All rights reserved

NOTICE OF COMPLETION
AND
AUTHORIZATION TO APPLY THE UL MARK

May 17, 2019

Mr. Dick Lee
3Y POWER TECHNOLOGY (TAIWAN) INC
2nd Fl 576,578 Minsheng N Rd Sec 1
Gueishan District
Taoyuan, 333, TW

Our Reference:	File E142723, Volume X3	Order	12738929
		Project	4788897585

Your Reference:	EH/SPC-1901022-app (Project 4788897585)
Project Scope:	UL and c-UL Component Recognition of Redundant Power Supply and Power Module / YVIC0300AH, etc. and YNEB0450BM, etc. / Report Ref#: E142723-A6022

Dear Mr. Dick Lee:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E142723, Volume X3.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site: http://www.ul.com/EAResponsibilities

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Elicia Sosa
Lead Project Engineer
Elicia.M.Sosa@ul.com

Reviewed by:

Bruce A. Mahrenholz
CPO Director
Bruce.A.Mahrenholz@ul.com

3bd1a2e2-8d52-4496-a676-91b1db5ac581

This is an electronically generated letter. Signatures are not required for this document to be valid.

3/3禁止翻印外洩 All rights reserved SFD-00004249-R03.pdf 建立時間:2020-03-24 17:26:39